

1. Initiator		2. Type of Review		3. RID Number
Name	LAST NAME FIRST Lunceford, James M.		<input type="checkbox"/> General Document Review	00200-206
Organization	DE-CLC		<input checked="" type="checkbox"/> PDR, CDR, ABR , PPR (circle)	
Phone	861-2294		<input type="checkbox"/> Other _____	
Fax	861-7470			
5a. Doc. Number	84K00200	6. Doc. Name	System Level Specification (SLS)	
5a. Doc. Revision	Pre-Release 1			
6. Name of RID Team		SLS RID Review Team		
7. Problem				
<p>2.1.1.1.2 lists orbiter hardware that the LDB gateway should be capable of accessing while in GSE mode. Several items have been left out (DEUs, command decoder MDM's).</p>				
8. Recommendation				
<p>All of the requirements specified in sections 2.1.1.1.2 through 2.1.1.1.5 are contained in the SS-P-0002-150 document specified in 2.1.1.1.1. Recommend deleting sections 2.1.1.1.2 through 2.1.1.1.5</p> <p style="text-align: right;"><input type="checkbox"/> Hardcopy of Redlines/Comments Attached</p>				
9. Impact if recommendation not implemented				
<p>Duplication of data may require that this document be changed when the SS-P-0002-150 changes.</p> <p style="text-align: right;">_____ Initiator - Signature Submission Date</p>				
10. Team Recommendation		11. Action Required		
<input type="checkbox"/> Accepted <input checked="" type="checkbox"/> Rejected <input type="checkbox"/> Study <input type="checkbox"/> Withdrawn <input type="checkbox"/> Deferred to CLCS CCB Screening Panel Comments See attachment. RID Team Manager - Signature _____		<input type="checkbox"/> Update Document <input type="checkbox"/> Study <input type="checkbox"/> Other (specify) _____ Comments		
12. Final RID Closure Action		13. Additional Comments/Notes		
<input type="checkbox"/> RID to be incorporated in next revision <input type="checkbox"/> RID to be incorporated in other (specify) RID Team Manager - Signature _____				

Due **NO LATER THAN** May 7, 1997

Response Attachment 200-206

The problem statement in this RID requests a change that is believed by the CLCS design team to be invalid for the following reasons:

1. When the LDB Gateway is in GPC mode (as defined in SS-P-0002-150) it does not have access to the command decoder MDMs. These MDMs are only directly accessible in DIO mode.
2. The GPC Gateway can not issue commands to the DEU. It may only communicate with the DEU through the DEU Equivalent TCS-1 command.

The RID Management Team agrees with this assessment. The RID is therefore rejected. Thank you for reviewing the SLS and submitting your RID. Even though we rejected this RID, your input is valuable and we appreciate it.